



Replacement Sheet

13/29



Typical Batch Operation



Typical Continuous Operation

Examples of traditional decision-making hierarchies


Figure 13

(Prior Art)



Traditional Approach

Replacement Sheet



Replacement Sheet



Traditional Production Scheduling

25/29

time Continuous operation with small grade transitions • Inflexible sequence of grade changes Wheel minimizes transition size and scheduling flexibility **Production Wheel Strategy** Off-spec production during transitions $\mathbf{\omega}$ Melt Index (Grade)

(Prior Art) Figure 25